

Oak & Pipe Plumbing

Sam Taylor

sam@example.com

COMPLETED WORK PHOTO REPORT

Bathroom tap replacement

Date: 2026-10-11

Client: Alex Morgan

Address: 12 Oak Lane

1. Tap replacement

Before



Old tap: worn handles and limescale.

Old tap replaced. No leaks after testing.

2. Final checks

Connections checked. Work area left clean.

After



New mixer fitted. Flow and seal checked.



Seal checked at the base.

Client signature

A handwritten signature in black ink, consisting of a series of sharp, jagged peaks and valleys, followed by a horizontal line.