Demo Plumbing

Demonstration technician

demo@example.com

COMPLETED WORK PHOTO REPORT

Bathroom tap replacement

Work date: Oct 11, 2026

Client: Demonstration customer

Address: Demonstration property

Summary

Fictional example. Photos, job details and signature demonstrate the app, not a customer case study.

1. Tap replacement

Before



Old tap: worn handles and limescale.

After



New mixer fitted. Flow and seal checked.

Old tap replaced. No leaks after testing.

2. Final checks

Connections checked. Work area left clean.



Seal checked at the base.

Client signature

